

SPCC PLAN CHECKLIST

Date of Investigation: 5/14/79

Time of Investigation: 0905

1) Facility Name: Duane Marine. 1.a) Owner:
 1.b) Operator:

2) Location: 26 Washington Street.
Porth Amboy.

3) Classification of facility: Treat

4) Nearest navigable water: Arthur Facility

5) Spill history indicated (for previous 12 months):

6) Responsible official: Ed. LECARREUX.

7) Management official: President.

8) P.E. certification:

9) Does Plan consider:

- a. Prediction of potential spills
- b. Facility drainage
- c. Topo maps
- d. Containment of bulk storage
- e. Facility for transfer operation
- f. Proper security
- g. Inspection and records procedure
- h. Training

10) Does Plan require construction of additional facilities?
If so, is it discussed in Plan (including schedule)

11) Storage capacity: 250,000 gallons - waste oils

12) Number of hours facility is manned:

13) NPDES Permit No. _____

14) Coast Guard Manual _____

General Appraisal: _____

Recommendation: _____

Signature of Investigator: Michael Volito

Date: 5/14/79



2